

Agriculture is Life!

**Ponding Test Results
Seepage and Total Losses,
Secondary Canals 13, 16, and 29
Donna Irrigation District
Hidalgo County No. 1**

Eric Leigh


Texas AgriLife Extension Associate, Biological and Agricultural Engineering, College Station

Guy Fipps

Texas AgriLife Extension Professor and Extension Agricultural Engineer, Biological and Agricultural Engineering, College Station

March 30, 2004

**PONDING TEST RESULTS
SEEPAGE AND TOTAL LOSSES,
SECONDARY CANALS 13, 16, AND 29
DONNA IRRIGATION DISTRICT
HIDALGO COUNTY NO. 1**



**PONDING TEST RESULTS:
SEEPAGE AND TOTAL LOSSES
SECONDARY CANALS 13, 16, AND 29**

**DONNA IRRIGATION DISTRICT
HIDALGO COUNTY NO. 1**

Report Prepared by:

Eric Leigh and Guy Fipps,¹ P.E.

March 30, 2004

IRRIGATION TECHNOLOGY CENTER

Texas Cooperative Extension - Texas Agricultural Experiment Station,
Texas A&M University System

¹ Extension Associate, and Professor and Extension Agricultural Engineer, respectively, Department of Biological and Agricultural Engineering, 2117 TAMU, College Station, TX 77843-2117.

CONTENTS

Summary

Table 1. Seepage loss rates measured in canals 13, 16, and 29, Donna Irrigation District Hidalgo County No. 1.

Table 2. Seepage loss rates of the canals 13, 16, and 29 in terms of change in water level.

Figure 1. View of the SJ9 test segment with staff gauge.

Figure 2. Map of district and close up of three test segments on the North Alamo Main Canal (DO1, DO2, & DO3).

Materials and Methods

Figure 3. Backhoe constructing earthen dam.

Figure 4. Upstream test dam used to seal test segment.

Test Results

Table 3. Data for Test SJ9: North Alamo Main Canal

Figure 5. Cross-section at Staff Gauge A, test SJ9.

Figure 6. Cross-section at Staff Gauge B, test SJ9.

Figure 7. Cross-section at Staff Gauge C, test SJ9.

Figure 8. Close up view of staff gauge stand in canal.

Table 4. Data for Test SJ10: North Alamo Main Canal

Figure 9. Cross-section at Staff Gauge A, test SJ10.

Figure 10. Cross-section at Staff Gauge B, test SJ10.

Table 5. Data for Test SJ11: North Alamo Main Canal

Figure 11. Cross-section at Staff Gauge A, test SJ11.

Figure 12. Cross-section at Staff Gauge B, test SJ11.

Figure 13. Dam that had been vandalized stopping the test.

CONTENTS (cont.)

Soil Descriptions

General Soil Series
Detailed Soil Units

Table 6. Soil Series Key Codes and Permeability Ranges.

Other Test Results

Table 7. Results of seepage loss tests conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.

Table 8. Results of total loss tests in lined canals conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.

Table 9. Results of total loss test in unlined canals conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.

Table 10. Canal seepage rates reported in published studies.

Acknowledgements

Ponding Test Results: Seepage and Total Losses, Secondary Canals 13, 16, and 29, Donna Irrigation District Hidalgo County No. 1

SUMMARY

This report summarizes the results of ponding tests conducted in Donna Irrigation District Hidalgo County No.1 (Donna) on July 22-24, 2003. Tests were conducted on three canal segments located in the northern portion of the district (see Fig. 2):

- Test segment DO1: west off of Val Verde Road, north of Mile 13 ½ N
- Test segment DO2: west off of Val Verde Road, north of Mile 15 N
- Test segment DO3: west of FM 493, south of Mile 15 N

DO1 was a seepage loss tests. However, test segments DO2 and DO3 contained turnout gates that may have contributed to measured losses; thus, the total losses were measured (Fig. 1).

Test results are summarized in Tables 1 and 2 and were as follows:

- The average seepage loss rate measured for Test Segment DO1 was 1.68 gal/ft²/day.
- Test Segment DO2 had four turnout gates (one turnout gate verified as leaking) and a 2 inch PVC pipeline may have contributed to the total loss rate of 2.18 gal/ft²/day.
- Test Segment DO3 had three turnout gates (unable to be verified as leaking) that may have contributed to the total loss rate of 2.71 gal/ft²/day.

Table 1. Summary of ponding test results of the canals 13, 16, and 29.							
Test ID	District Segment ID	Soil*	Length (ft)	Avg. Width (ft)	Test Type	Loss rate Gal/ft ² /day	Total Loss in Canal (ac-ft/mile) per day per year
DO1	Lat 13	Sandy clay loam	1500	4.6	seepage	1.68	0.18 65.2
DO2	Lat 16	Sandy clay loam	1500	6.0	total**	2.18	0.33 121.5
DO3	Lat 29	Sandy clay loam	1500	5.9	total**	2.71	0.29 107.2

* Soil type of the surrounding area from the Soil Survey for Hidalgo County (USDA 1978)

** turnout gates located within the test segment may have contributed to losses

Table 2. Test results for canals 13, 16, and 29 in terms of change in water level.				
Test ID	ft/hr	ft/day	in/hr	in/day
DO1	0.017	0.41	0.20	4.91
DO2	0.023	0.55	0.28	6.64
DO3	0.033	0.79	0.40	9.47



Figure 1. Large cracks and turnout gates shown above contribute to higher total losses of canal segments.




Figure 2. District Map and locations of test segments.

MATERIALS AND METHODS

Canal loss rates were measured using the ponding method. In this method, the two ends of a canal segment are closed or sealed with earthen dams as shown in Figure 3. Once sealed, water elevations are taken for approximately 48 hours. Two staff gauges (Fig. 4) were placed in each test segment, and stage levels were recorded manually. Canal dimensions and water spans were also surveyed during the test.

The tests are classified as follows:

- Test segment DO1 did not contain valves or gates within the canal; thus, the seepage rate was measured.
- Test segment DO2 and DO3 contained several leaking turnout gates (Fig. 5); thus, we classify this as a total loss test since the gates contributed to the measured losses.

Tables 3, 4, and 5 provide details on the test segments, data collected and recorded changes in water depths during the tests. The canal cross-sections at each of the staff gauges are illustrated in Figures 6 - 7 for test DO1, Figures 8 - 10 for test DO2, and Figures 11 - 12 for test DO3. Also shown on these charts are the water depths at the beginning of the test.



Figure 3. One of the earthen dams used in the ponding tests.



Figure 4. Staff gauge use to measure water levels.



Figure 5. A leaking turnout gate leak found in Test Segment DO2.

Table 3. Data for Test DO1: Lateral 13.				
District: Donna Irrigation District Hidalgo County No. 1			Test ID: DO1	
Canal: Lateral 13			Lining Type: Lined	
Starting Water Span Widths: A: 3.54 feet, B: 4.5 feet			Date: Jul 22-24, 2003	
Test Segment Length: 1500 feet			Start Time: 4:09 pm Finish Time: 3:59 pm	
Test Starting Depths: A: 1.62 feet, B: 2.27 feet				
Location: west off of Val Verde Road, north of Mile 13 ½ N				
Staff Gage Readings				
Date	A		B	
	Time	Feet	Time	Feet
Jul 22	16:09	1.19	16:08	5.0
	18:12	1.09	18:10	4.89
	19:33	1.05	19:29	4.85
Jul 23	09:47	0.70	09:46	4.5
	13:50	0.64	13:49	4.45
	16:58	0.60	16:56	4.4
Jul 24	11:02	0.41	11:01	4.22
	15:59	0.38	15:58	4.18
True depth adjustment factor (ft)		0.427		-2.73




Figure 6. Cross-section at Staff Gauge A, DO1.



Figure 7. Cross-section at Staff Gauge B, DO1.

Table 4. Data for Test DO2: Lateral 16.				
District: Donna Irrigation District Hidalgo County No. 1			Test ID: DO2	
Canal: Lateral 16			Lining Type: Lined	
Starting Water Span Widths: A: 4.7 feet, B: 6.1 feet			Date: Jul 22-24, 2003	
Test Segment Length: 1500 feet			Start Time: 11:56 am Finish Time: 1:50 pm	
Test Starting Depths: A: 2.75 feet, B: 2.90 feet				
Location: west off of Val Verde Road, north of Mile 15 N				
Staff Gage Readings				
Date	A		B	
	Time	Feet	Time	Feet
Jul 22	11:56	1.38	11:58	4.82
	13:48	1.16	13:47	4.60
	16:01	0.98	15:59	4.42
	17:43	0.90	17:43	4.34
	19:55	0.82	19:54	4.26
Jul 23	09:55	0.56	09:53	4.00
	13:59	0.50	13:58	3.94
	16:49	0.46	16:47	3.90
Jul 24	11:09	0.25	11:07	3.70
	13:47	0.22	13:50	3.67
True depth adjustment factor (ft)		1.373		-1.916




Figure 8. Cross-section of Staff Gauge A, DO2.



Figure 9. Shows test segment DO2 with serious structural problems that has been repaired many times over, and since has change the shape (see Fig. 8).




Figure 10. Cross-section of Staff Gauge B, DO2.

Table 5. Data for Test DO3: Lateral 29.				
District: Donna Irrigation District Hidalgo County No. 1			Test ID: DO3	
Canal: Lateral 29			Lining Type: Lined	
Starting Water Span Widths: A: 4.85 feet, B: 5.4 feet			Date: Jul 22- 24, 2003	
Test Segment Length: 1500 feet			Start Time: 4:19 pm Finish Time: 3:35 pm	
Test Starting Depths: A: 1.79 feet, B: 2.13 feet				
Location: west of FM 493, south of Mile 15 N				
Staff Gage Readings				
Date	A		B	
	Time	Feet	Time	Feet
Jul 22	16:22	1.73	16:19	2.13
	17:30	1.61	17:28	2.01
	18:35	1.53	18:30	1.93
	20:06	1.43	20:04	1.84
Jul 23	10:08	1.10	10:09	1.23
Jul 24	10:53	0.43	10:52	0.65
	15:30	0.16	15:35	0.59
True depth adjustment factor (ft)		0.062		0.00



Figure 11. Cross-section for Staff Gauge A, DO3.




Figure 12. Cross-section for Staff Gauge B, DO3.

SOIL DESCRIPTIONS

General Soil Series

1 – Hidalgo: Deep, moderately permeable soils that typically have dark grayish brown sandy clay loam surface layer (source: Soil Survey of Hidalgo County, Texas USDA, 1978).

Detailed Soil Units

Table 6. Soil Series Key Codes and Permeability Ranges.	
Soil Unit	Permeability (in/hr)
28 – Hidalgo sandy clay loam	0.6 – 2.0

OTHER TEST RESULTS

Texas Cooperative Extension has conducted approximately 50 total loss tests and seepage loss tests in the Lower Rio Grande River Basin since 1998. The results are summarized in Tables 7 – 9. Table 10 gives seepage rates versus lining type as reported in the scientific literature.

Table 7. Results of seepage loss tests conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.						
Test ID	Year	Canal Width (ft)	Canal Depth (ft)	Class	<u>Loss Rate</u> gal/ft2/day ac-ft/mi/yr	
<u>Lined</u>						
16HC2	03			M		
LF1	03	12	5	M	1.77	152.9
LF2	03	10	6	M	4.61	369.1
MA4	03	12	5	S	8.85	529.7
SJ4	00	15	4	M	1.17	111.2
SJ5	02	14	5	M	1.38	145.5
UN1	01	12	6	M	2.32	217.7
UN2	01	8	3	M	2.09	121.2
<u>Unlined</u>						
BR1	03	60	11	M	3.14	794.6
MA3	03	19	5	S	13.9	1690.1
RV1	03	38	4	M	0.15	23.0
SB4	02	16	4	S	0.64	68.3
SB5	02	18	3	S	1.67	188.3
SB6	02	20	5	S	1.44	189.0
SB7	02	16	4	S	0.42	47.4
SB8	02	20	5	S	0.83	104.0

Classification of canal: M = main, S = secondary

Table 8. Results of total loss tests in lined canals (leaking gates and valves may have contributed to measured loss rates) conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.

Test ID	Year	Canal Width (ft)	Canal Depth (ft)	Class	<u>Loss Rate</u>	
					gal/ft2/day	ac-ft/mi/yr
<u>Lined</u>						
16HC1	03	14	5	M	1.89	192.4
BV1	99	10	5	M	7.97	510.5
BV2	99	9	4	M	8.53	451.5
DL1	00	20	6	M	0.16	18.8
DL2	00	7	4	S	4.12	236.2
DO1	03	5	3	S	1.68	65.2
DO2	03	6	4	S	2.18	121.5
DO3	03	6	3	S	2.71	107.2
ED1	00	6	4	S	34.32	1519.6
ED2	00	6	4	S	21.5	858.2
ED3	00	3	2	T	10.22	308.2
ED4	00	4	3	S	18.72	567.7
ED6	99	9	4	M	8.53	451.5
HA2	00	10	4	M	2.26	135.2
HA3	98	15	2	S	0.64	45.5
ME1	98	38	7	M	1.26	281.9
ME2	98		4	M	1.88	163.5
SJ1	99	12	5	M	2.58	126.8
SJ6	03	12	3	M	1.88	1.63
SJ7	03	19	4	M	1.98	227.1
UN3	02	12	6	M	2.02	154.3

Classification of canal: M = main, S = secondary, T = tertiary

Table 9. Results of total loss tests in unlined canals (leaking gates and valves may have contributed to measured loss rates) conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.						
Test ID	Year	Canal Width (ft)	Canal Depth (ft)	Class	<u>Loss Rate</u>	
					gal/ft ² /day	ac-ft/mi/yr
BV3	99	55	8	M	0.15	53.4
ED5	02	105	7	M	2.39	1213.2
MA1	99	50	10	M	1.98	227.1
MA2	99	20	5	S	4.32	371.4
SB1	00	29	7	S	1.27	215.5
SJ2	00	23	6	M	2.74	293.2
SJ3	00	30	5	S	0.95	132.6

Classification of canal: M = main, S = secondary

Table 10. Canal seepage rate reported in published studies.	
Lining/soil type	Seepage rate (gal/ft²/day)
Unlined ¹	2.21-26.4
Portland cement ²	0.52
Compacted earth ²	0.52
Brick masonry lined ³	2.23
Earthen unlined ³	11.34
Concrete ⁴	0.74 - 4.0
Plactic ⁴	0.08-3.74
Concrete ⁴	0.06-3.22
Gunit ⁴	0.06-0.94
Compacted earth ⁴	0.07-0.6
Clay ⁴	0.37-2.99
Loam ⁴	4.49-7.48
Sand ⁴	4.0-19.45

¹ DeMaggio (1990). Technical Memorandum: San Luis unit drainage program project files. US Bureau of Reclamation, Sacramento. ² U.S. Bureau of Reclamation (1963). Lining for Irrigation Canals. ³ Nayak, et al. (1996). The influence of canal seepage on groundwater in Lugert Lake irrigation area. Oklahoma Water Resources Research Institute. ⁴ Nofziger (1979). Profit potential of lining watercourses in coastal commands of Orissa. Environment and Ecology 14(2):343-345.

ACKNOWLEDGEMENTS

Funding

A portion of this study was funded by Texas Cooperative Extension through the Irrigation Conservation in the Rio Grande Basin Initiative administered by the Texas Water Resources Institute of the Texas A&M University System with funds provided through a grant from Cooperative State Research, Education, and Extension Service, U.S. Department of Agriculture, under Agreement No. 2001-001-45049-01149.

Irrigation District Engineering and Assistance (IDEA) Team

Biological and Agricultural Engineering
2117 Texas A&M University
College Station 77843-2117
979-845-3977

Guy Fipps, Professor and Extension Agricultural Engineer
Dave Flahive, System Analyst

Texas A&M Research and Extension Center
2401 US Highway 83,
Weslaco 78596-8398
956-968-5581

Eric Leigh, Extension Associate
Martin Barroso, Ag Technician
Noemi Perez, Ag Technician

Web Address: <http://idea.tamu.edu>

THE IRRIGATION TECHNOLOGY CENTER

A center of the Texas Water Resources Institute

Texas Cooperative Extension - Texas Agricultural Experiment Station,
Texas A&M University System
<http://itc.tamu.edu>